

TECHNICAL SERVICE BULLETIN

76-B-11

NO.



Triumph

November, 1976

SUBJECT:

INCORRECT POSITIONING OF HORN RELAY


MODELS:

TR7


Cases have been reported where the horn relay on the TR7 has been installed in such a position as to allow water ingress.

Please check this item during pre-delivery and/or during the next customer regular servicing interval, and if necessary re-position as shown in the diagram.

A Warranty Time for this operation of 00.30 hours will be allowed.



INCORRECT POSITION



CORRECT POSITION

J.P.