

# TECHNICAL SERVICE BULLETIN



# Triumph

NO.

May, 1977

SUBJECT:  
 TIME CLOCK CLAMP BRACKETS

MODELS:  
 TR7

Replacement time clocks, part No. UKC 2408, are not supplied complete with clamp brackets.

It is therefore necessary to retain the clamp bracket from the displaced instrument for use with the replacement clock.

T-04-77/67

Provided Courtesy Triumph Wedge Owners Association  
<http://www.triumphwedgeowners.org>