

NO. 79/2/4-A



Recall Campaign Bulletin

SUBJECT:RECALL CAMPAIGN A457
HEADLAMP MOTOR**MODELS:**

1975-78 TR7

March, 1980

All defective headlamp motors (P/N PKC1287/K) replaced under this recall campaign are to be returned to your Zone/Distributor Warranty Department. See Section 17 of the Warranty Policy and Procedure Manual 1978-79.

When replacing complete motor assembly/limit switch (P/N PKC 1287/K) it will not be necessary to inspect the attached limit switch.

Provided Courtesy Triumph Wedge Owners Association
<http://www.triumphwedgeowners.org>