



TECHNICAL SERVICE BULLETIN



Date...Nov./Dec...1981

ITEM T81/20

SUBJECT: AC DELCO IGNITION

MODELS: TR7 from engine #CV30570

Dealers are reminded that Technical Service Bulletin dated May 1981, Item T81/08 states that complete coil assemblies must not be replaced for suspected failure of the module unit.

Electronic ignition modules are available as separate units under part number JRT 601011. Warranty claims for complete GCL 128 coil replacement will not be accepted without specific authorization from District Service Managers or the Zone Service Department.

The following repair operation time information applies:

REPAIR OPERATION 86.35.35 - Remove/Replace Ignition Module - 0.40 hours

H.C.T.