

# TECHNICAL SERVICE BULLETIN

NO. 75-D-6A



# Triumph

June, 1975

**SUBJECT:**

**SELECTOR SHAFT YOKE PLASTIC BUSH  
WORKING LOOSE**

**MODELS:**

**SPITFIRE 1500 & TR7**

Further to Service Bulletin No. 75-D-6, dealers have reported difficulty in obtaining Loctite 636. However, its equivalent is Loctite 307, which should be available locally.

In the event that any further difficulty is experienced in obtaining Loctite 307, please advise your Distributor or District Service Manager immediately.

J.P.