

# TECHNICAL SERVICE BULLETIN

77-B-1

NO.



# Triumph

April, 1977

SUBJECT:

HEAD LAMP FEED WIRE SECURITY


MODELS:

TR7

When installing head lamp assemblies on the TR7, extra care should be taken to insure that the lamp feed wire is routed in such a manner so as to prevent it from becoming trapped in the closed position, between the top of the actuating motor and the base of the lamp tray assembly (refer to diagram).

continued.....

Triumph



J.P.