ITEM 81A/22

SUBJECT: 1981 PASSPORTS TO SERVICE

MODELS: All

To comply with the terms of Section 207b of the Clean Air Act, all 1981 model year vehicles require a special Passport to Service:

Jaguar - SER 8-1180 Triumph - SR 10-581

The proper Passports are being inserted in the literature packs at the P.O.E. prior to shipment to the dealers. You are requested to make certain the correct Passport is delivered to the owner. Details of Section 207b may be found in Technical Service Bulletin 80A/32.

Dealers are also reminded of the Federal requirements on all 1981 model year cars, to complete and supply to the customer a copy of the <u>Dealer Certificate of Conformity</u>, (SER 73 Revised 880). Correct procedures are outlined in Technical Service Bulletin 80A/36.

Note deliveries of 1980, 1979 vehicles do not require the use of the revised PDI form.

P.W.B.