



# TECHNICAL SERVICE BULLETIN



Date August, 1980

ITEM T80/020

SUBJECT: ALTERNATOR HARNESS ROUTING

MODELS: TR7 (w/Lucas A133 Alternators)

TR7 vehicles fitted with A133 Lucas alternators, which can be recognized by the single stud connection at the alternator as opposed to a Lucar terminal block, should be checked during routine service, for proper alternator harness run and location.

The harness run should be clear of the lower radiator hose and secured properly in the harness clip on the motor mount.

H.C.T.