

Parts and Accessories INFORMATION Bulletin

January 1982

82-IB-8

SUBJECT: MODEL 65 BORG WARNER
AUTOMATIC TRANSMISSION

MODELS: Jaguar XJ6 Series II and III
Triumph TR7 and TR8

The detent shaft, RTC 86, is no longer available from Borg Warner and necessitates a multiple supersession.

To replace RTC 86 use the following:

AEU 1071	- Detent Shaft	1
AEU 1070	- Detent Lever	1
AEU 1076	- Pin	1
AEU 1072	- Spacer	1
AEU 1618	- Wavey Washer	A/R

Cars which are 1980 models or have Model 66 transmissions should already be equipped with the newer condition parts. An illustration is shown overleaf for your convenience.

Parts Sales & Marketing Department

DW/pt

over . . .



AUTOMATIC TRANSMISSION - Parking Linkage
 XJ6 II, III, TR7, TR8

