

TECHNICAL SERVICE BULLETIN

NO



Triumph

July, 1977

SUBJECT: CAMSHAFT COVER OIL LEAKS	MODELS: TR7
--------------------------------------	----------------

To prevent the possibility of oil seepage in the area of the camshaft rubber end plugs, it has been found beneficial to apply GE clear sealing compound to the face of the cylinder head recess prior to fitting the plugs into the cylinder head. The surfaces should be perfectly clean and free of oil when carrying out this operation.

T-08-77/86

Provided Courtesy Triumph Owners Association
<http://www.triumphweb.com>
Triumph Owners Association