

# TECHNICAL SERVICE BULLETIN

77-B-9

NO.

BRITISH



LEYLAND

# Triumph

August, 1977

B  
E  
E  
E

SUBJECT:

REVISED HORN RELAY

MODELS:

TR7

A new improved horn relay was introduced at VIN #ACW10719. The part number of the new relay is DRC131.

T-09-77/114

Provided Courtesy Triumph Wedge Owners Association  
<http://www.triumphwedgeowners.org>