

# TECHNICAL SERVICE BULLETIN

NO.

77-D-2

BRITISH



LEYLAND

# Triumph

January, 1977

SUBJECT:

REVERSE GEAR RATIO

MODELS:

TR7

Please note the reverse gear ratio changed from 3.011;1 to 3.053;1. This change is effective from VIN ACW-4417 approximately.

EN/20/37

Provided Courtesy Triumph  
<http://www.triumphwebowners.org>