ITEM 80A/08

SUBJECT: SOFT TOP REPLACEMENT

MODELS: A11

Effective March 1, 1980, should it become necessary to replace a convertible soft top under warranty, the following top kits are to be used: D/N BLM-1054112
'N ELM-105409

| Spitfire | P/N | BLM-10541 | 3 |
|----------|-----|-----------|----|
| Spittife | P/N | BLM-1054 | Τ. |

TR7

MGB

Midget

As these kits include just the top material less hardware and frame, it will be necessary to remove and reuse the bows, etc.

| Time a | allowance: | TR7 | 1.8 hours | MGB | 1.4 hours |
|--------|------------|----------|-----------|--------|-----------|
| | | Spitfire | 1.4 hours | Midget | 2.8 hours |

If it becomes necessary to replace a top assembly due to structural damage from accidents, etc., complete assemblies are available by special order. Trim and top replacement/repairs under the terms of the vehicle warranty require prior authorization.

P.W.B.







