

# Parts and Accessories INFORMATION Bulletin

April 1982


82-IB-32

SUBJECT: CRANKSHAFT PULLEYS

MODEL: TR7 - all years

The fiche illustration is somewhat misleading regarding the positioning of the crankshaft pulley(s), especially when air conditioning is involved.

You may find this illustration helpful where questions arise.



Parts Sales & Marketing Department  
DW/pt

