

TECHNICAL SERVICE BULLETIN



ITEM T80/013
SUBJECT: RADIO INSTALLATION TR7 30th ANNIVERSARY MODEL
MODELS: TR7

Special new auto-reverse cassette radio, part for the control of the contro be taken to see that the wiring harness is clear of the back of the radio when inserted into the dash to avoid pinched wires.

In addition, due to the longer (deeper) chassis, there can possibly be some interference with the insulation pad (up to 4" thick) on the transmission tunnel and the bottom of the radio. On some vehicles, it is necessary to remove a small section of the insulation, even with the bottom of the radio, to permit the radio to be installed flush in the dash.